DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019555

Address: 333 Burma Road **Date Inspected:** 17-Nov-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes N/A No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 10

This QA Inspector observed the following work in progress for Bay 10.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Li Peng Fei.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; Bike Path PCMK: BK004A2-028

Weld No. 002, 008, 013, 021 Welders: 053869, 040533, 052075

WPS-B-T-2132

Component; OBG splice channel PCMK: GGL-MQ-1958-21~32

Weld No. 001, 002



WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Welder: 052763

WPS-B-T-2232-TC-U4b-F

This QA Inspector observed the following work in progress for Bay 10.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Li Peng Fei.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; Bike Path PCMK: BK004B6-025 Weld No. 002, 008, 013, 021

Welder: 040302 WPS-B-T-2112

Bay 12

This QA Inspector observed the following work in progress for Bay 12.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is not identified for mockup.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; Hand Rail Mockup PCMK: BKR-NS-10 & 36

Welder: 053869 WPS-B-T-2234

Bay 14 west

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Ji Cai Feng.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; OBG 13AW

PCMK: FB3193A Weld No. 177, 178 Tack Welder: 040302 WPS-B-T-2112

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No significant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Leavitt,Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer